







1/14

Fig. 1



Fig. 2Fig. 3


Fig. 4

4/14

Fig. 5Fig. 6

5/14


Fig. 7Fig. 8

Fig. 9


7/14

Fig. 10

$$B = 50; \delta = 0.1; h_p = 1.25; S_p = 0.13$$

Fig. 11

$$B = 50; \delta = 0.1; h_p = 1.25; S_p = 0.13$$



8/14

FIG. 12(a)





FIG. 12(b)

9/14

FIG. 12(c)






FIG. 12(d)

10/14

Fig. 13

11/14





Fig. 14

12/14

Fig. 15





Fig. 16

Fig. 17